## **FINAL REPORT**

## CERTIFICATE No.: 25859

BORAL

Boral Cement Limited ABN 62 008 528 523 Taylor Avenue New Berrima NSW 2577 Locked Bag 4 New Berrima NSW 2577 T +61 2 4860 2222

| TEST CERTIFICATE OF:   | Marulan Quicklime Fines - Despatch Composite |  |
|------------------------|--|--|
| PRODUCED AT:           | Boral Cement Limited Marulan                 |  |
| TESTED AT:             | Berrima Works Laboratory                     |  |
| SAMPLE IDENTIFICATION: | LDQLF2401201                                 |  |
| DATE SAMPLED:          | for date ending 9/03/2024                    |  |

| PROPERTY                                    | RESULT    |  |
|---|-----------|--|
| Chemical Composition (AS 4489.5.1)          |           |  |
| CaO   | 92.1 %    |  |
| MgO   | 0.9 %     |  |
| Al <sub>2</sub> O <sub>3</sub>              | 0.5 %     |  |
| SiO <sub>2</sub>                            | 1.4 %     |  |
| K <sub>2</sub> O                            | 0.1 %     |  |
| Fe <sub>2</sub> O <sub>3</sub>              | 0.4 %     |  |
| LOI (AS 4489.7.1)                           | 4.8 %     |  |
| ALI as CaO (AS 4489.6.1)                    | 87.0 %    |  |
| Slaking (AS 4489.3.1)                       |           |  |
| Temperature Rise at 30 s                    | 21.5 °C   |  |
| Temperature Rise at 3 min                   | 36.0 °C   |  |
| Total Temperature Rise                      | 41.5 °C   |  |
| Total Active Slaking Time                   | 10.0 mins |  |
| Residue on Slaking                          | 1.61 %    |  |
| Particle Size Distribution * (AS 1141.11.1) |           |  |
| < 4.75 mm                                   | 100 %     |  |
| < 2.36 mm                                   | 100 %     |  |
| < 1.18 mm                                   | 98 %      |  |
| < 600 µm                                    | 91 %      |  |

## REMARKS

Sampling not carried out by laboratory. Samples tested as received and results only relate to the item tested. \* Samples are not washed.



 $\mathcal{N}$ 

Marc Smith Technical Services Manager